



SUSPENSION OF ATS SERVICES WITHIN THE CURACAO FIR TO AIRLINE CONVIASA-CONSORCIO VENEZOLANO DE IND.

Effective date: 05 MAY 2017

Effective 05 MAY 2017: DC-ANSP will suspend Air Traffic Services within the CURACAO FIR to all aircraft of **CONVIASA-CONSORCIO VENEZOLANO DE IND.**, operating under ICAO code **VCV**, including the following aircraft registrations operating or operated under ICAO code **VCV**:

- **YV1004 , YV1005 , YV1009**
- **YV2421 , YV2422**
- **YV2849 , YV2850 , YV2851**
- **YV2911 , YV2912 , YV2913 , YV2943 , YV2944**
- **YV2953 , YV2954 , YV2964 , YV2965 , YV2966**
- **YV3016 , YV3052 , YV3071**

And all other aircraft operating for **CONVIASA-CONSORCIO VENEZOLANO DE IND.**, due to lack of compliance with DC-ANSP Dutch Caribbean AIP GEN 4.2