

**EFFECTIVE DATE: 28 DECEMBER 2022**

*This supplement hereby supersedes TNCC AD 2 Aerodrome Chart – AD 2 TNCC-34 – 06 OCT 22. The below information/ data has been amended and will be placed in the Dutch Caribbean AIP at the earliest opportunity.*


**TNCC Aerodrome Chart - Update**

This Supplement indicates the replacement of the TNCC Aerodrome Chart published in the AIP (AD2 TNCC-34).

**Revised part on chart:**

In the actual TNCC Aerodrome Chart the information, containing the Runway 11 RESA dimension, was not clear. The information is adjusted, so that the RESA dimension is more readable.

The illustration below is a zoom-in on the TNCC AD Chart (*pink highlighted section*), indicating where the change has taken place.



Please refer to the next page for the updated version of the TCC Aerodrome Chart.


For additional information, please contact the CAP Airside Operations at (+5999) 839-1030.

*Any questions and/or remarks, please contact the DC-ANSP AIS department Curaçao as soon as possible via above mentioned email address ([aipaim@dc-ansp.org](mailto:aipaim@dc-ansp.org))*

Kaya Afido z/n  
Seru Mahuma  
Curaçao

Phone : (599-9) 839-3550 ext. 510/523/514  
Telefax : (599-9) 868-3012  
AFS : TNCCYNYX  
E-mail : [aipaim@dc-ansp.org](mailto:aipaim@dc-ansp.org)

**AIP  
SUPPLEMENT  
28/22  
28 DEC 2022**



CHANGES - New Chart